

### **TEST CERTIFICATE**

Site Number
Transaction Number

840-Emirates Auctions

13391729 (CC10006)

Transaction Date

09 Oct 2021, 18:03:48

Queue Number 312309

Chassis Number

5NPE24AF5GH348061

**Engine Number** 

Vehicle Class Car

Manufacturer Hyundai

Model Sonata

Model Year 2016

Color White

Mileage 122085 Km



**REMARKS DEFECT** 01 Body جسم المركبة 01.A Fenders **REPAIRED & REPAINTED** مدكار PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON 01.B Paint الصبغ BODY REAR BOTH SIDE, TRUNK REPAIRED & REPAINTED 01.C Doors أبواب 01.D Rusty UNDER BODY PARTS GETTING RUSTY صدأ 01.E Floor **UNDER BODY COVERD** الارضية 01.F Bumper **REPAINTED** دعامية 01.G Bonnet **REPAIRED & REPAINTED** غطاء المحرك 01.H Other REAR BACK PANEL, SPARE WHEEL HOUSING, QUATER اخري PANEL & FRONT BUMPER FRAME FENDER BRAKET REPAIRED 02.A Chassis **REAR BOTH SIDE REPAIRED** 

**02 Chassis Condition** الشاصي الشاسيه **03 Engine Condition** المحرك 03.A Other ОК اخری **04 Seats Condition** المقاعد 04.A Other REAR COVER SPOT DAMAGED اخری **05 Transmission Condition** الجير 05.A Gear Box OK الجير

DEFECT	REMARKS	
06 Brake Condition		الفرامل
06.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH 2018	الاطار الامامي
07.B Rear Tyre	BOTH 2018	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	ОК	اخري
08.C Tail Light	RIGHT SIDE PARK LIGHT NOT WORKING	الانارة
09 Wipers and Arms		المساحات
09.A Other	WORN OUT	اخري
10 Interior Condition		الاجزاء الداخلية
10.A Other	ОК	اخري
10.B Mirror	OK	المرايا
10.C AC Condition	OK	المكيف
11 Steering Condition		المقود
11.A Steering Boot	BOOT LEAKING	ربلة المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# **Test Certificate**









Possession Certificate: 65673560

Chassis No : 5NPF24AF5GH348061 Vehicle Make: HYUNDAI Vehicle Model: SONATA

Vehicle Class: Light Vehicle SALOON **Body Type:** Fuel: Benzene Color: White

**Drive Direction:** Left Hand Side

Dimensions: (H x W x L) --x--x--Current Odometer : 196484 Kms

Origin: United States

Gear Type: Automatic Engine No: Axles No:

No Of Doors: 4 G. V. W.: 2100 Kas

Model Year: 2016

**Engine Size:** 2000 CC **Horse Power:** 185 Cylinders:

No Of Seats:

Empty Weight: 1500 Kgs.

Certificate Number: 5-TAS-2021-15248390

Inspection Date: 16-10-2021 Certificate Print Date : 16-10-2021 Services: Registration Test

Vehicle Testing Partner: Tasjeel

Vehicle Testing Center: Tasjeel Al Aweer

Total Time Taken: 13 min 50 sec

Appointment Ref Number : --

Start Time: 16:21 Lane: Attempt: 1

End Time: 16:35 Token No.: 184 Prints No: 1

Carbon footprint



Keep protecting Dubai environment

### Estimated Vehicle Consumption (Rate last 12 Months)



year

26695 KM Distance per Fuel consumed

1897 I

per year

3074 AED Fuel cost per vear

4.6 ton Carbon footprint per year

### **Parameter Readings**

Service brake imbalance on front axle

7%

Service brake imbalance on rear axle 7%

Parking brake imbalance between LHS and RHS 12 %

Vehicle on Petrol CO Reading 0%

Vehicle on Petrol HC Reading 1 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	2000	2400	

#### Inspection Remarks:

front right side frame member end dent & rear right end repaired/front & rear bumper/back panel/radiator frame bonnet repaired(OLD/) & tire need alignment / CHANGE FRONT TIRE

## **Payment Details**

Inspection Performed by 33695 59460 59460 - -

**Parking Slot No** 

**Payment Method** 

**Transaction Number** 15248390

Service Fees

AED 170 Collected on 16/10/2021

**Service Name** Registration Test

**Attempt** 

Received by Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30 يود من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.