



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Dec 2021, 18:13:12
Transaction Number	74789609 (CC10006)	Queue Number	312309



Chassis Number	5NPD84LFXJH290544
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Elantra
Model Year	2018
Color	White
Mileage	90947 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
01.B Doors	LEFT SIDE BOTH DOOR REPAINTED,REPAIRED,REFITIED	أبواب
01.C Fenders	REAR BOTH SIDE FENDER REPAINTED,PORTION REPAIRED& FRONT BOTH SIDE REPAINTED,REFITIED	مدكار
01.D Bumper	REPAINTED	دعامية
01.E Roof	PORTION REPAIRED,REPAINTED	السقف
01.F Bonnet	REPAINTED	غطاء المحرك
01.G Floor	FRONT LEFT SIDE FLOOR REPAIRED	الارضية
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة
01.I Trunk	REPAIRED,REPAINTED	صندوق
02 Interior Condition		الحالة الداخلية
02.A Air Bag	LEFT SIDE AIR BAG DAMAGED	وسائد هوائية
02.B AC Condition	OK	المكيف
02.C Sun Visor	LEFT SIDE MIRROR BROCKEN	حاجب الشمس
03 Lights		الاضاءة
03.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

DEFECT	REMARKS	
03.B Head Light	ALL LIGHT WORKING	الاضاءة الرئيسية
04 Chassis Condition		الشاسي
04.A Chassis	FRONT LEFT SIDE LOWER PORTION BEND	الشاسيه
05 Battery Condition		حالة البطارية
05.A Battery Condition	OK	حالة البطارية
06 Engine Cooling System		نظام تبريد المحرك
06.A Radiator Hose	RADIATOR WATER LEAK	خرطوم المبرد
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2018/2019	الاطار الخلفي
07.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
08 Engine Condition		المحرك
08.A Engine Condition	REFITIED,OIL SUMB MINOR DENT	حالة المحرك
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	REFITIED	الجير
10 Seats Condition		المقاعد
10.A Seat Belt	OK	حزام الأمان
10.B Seat Condition	OK	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	5NPD84LFXJH290544
Vehicle Make :	HYUNDAI
Vehicle Model :	ELANTRA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	146382 Kms.
Origin :	United States
Model Year :	2018
Gear Type :	Automatic
Engine Size :	2000 CC
Engine No :	NIL
Horse Power :	--
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1500 Kgs. 1800 Kgs.

Certificate Number :	5-TAS-2022-15838045
Inspection Date :	06-01-2022
Certificate Print Date :	06-01-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Qusais
Total Time Taken :	6 min 26 sec
Appointment Ref Number :	--
Start Time :	19:02
End Time :	19:09
Lane :	03
Token No. :	588
Attempt :	1
Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



192 KM

Distance per
year



14 L

Fuel consumed
per year



23 AED

Fuel cost per
year



0.1 ton

Carbon footprint
per year

Parameter Readings

Service brake imbalance on
front axle
1 %

Service brake imbalance on
rear axle
14 %

Parking brake imbalance
between LHS and RHS
13 %

Vehicle on Petrol CO
Reading
0 %

Vehicle on Petrol HC
Reading
4 PPM VOL

Inspection Remarks:

FRONT BUMPER FRAME , LEFT SIDE FENDER , FENDER FRAME AND WHEEL ARCH REPAIRED // FRONT LEFT SIDE CHASSIS REPAIRED & DENT // CCM PASSED WORK ORDER #2021-01-06-8

Payment Details

Inspection Performed by
33669

Parking Slot No
--

Payment Method
Cash

Service Name
Registration Test

Transaction Number
15838045

Attempt
1

Service Fees

AED 170 Collected on 06/01/2022

Received by

Mohammed Ahmed Mohsen
Albaidhani

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

