CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3041803
Transaction Date	27 Nov 2026, 14:25:16
Site Name	840 - Emirates Auctions
Transaction Number	60221391 (CC10010) (CC10011)

Vehicle Details

Chassis Number	WP0ZZZ97ZA*******
Specification	Imported
Make	Porsche
Model	Panamera
Model Year	2010
Color	Black
Mileage	122051 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED REPAINTED,MINOR DENT SCRATCHES	الصبغ
01.B Doors	REAR BOTH SIDE REFITTED,RIGHT PORTION REPAIRED REPAINTED	أبواب
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED , .CHECKED ONLY VISIBLE AREA .	الارضية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	COMPONENT PARTS GETTING RUSTY.MINOR SHAKING.	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	COMPONENT PARTS GETTING RSTY, MINOR OIL WET.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2020 CRACKED EXPIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 CRACKED EXPIRED	الاطار الخلفي
05.C Rims Condition	ALL WHEEL NUT RUSTY.	حالة الجنوط

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Tail Light	GETTING CRACK	الضوء الخلفي
06.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR BOTH SIDE MINOR LEAK.	ممتص الصدمات
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PORTION MODIFIED	اخري
09.B AC Condition	LOW COOLING NOT WORKING PROPERLY,ADJUSTMENT NOT WORKING PROPERLY	المكيف
09.C Dash Board	LEATHER LOOSE PORTION DAMAGED	لوحة القياده
09.D Roof Ceiling	FRONT RIGHT SIDE PORTION LOOSE.	بطانه السقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae