CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945763
Transaction Date	05 Nov 2026, 16:45:10
Site Name	840 - Emirates Auctions
Transaction Number	72262170 (CC10009) (CC10019)



Vehicle Details

Chassis Number	KNALN4141C*******
Specification	GCC Specification
Make	Kia
Model	Cadenza
Model Year	2012
Color	White
Mileage	115331 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE, REAR RIGHT SIDE REPAINTED,PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED GETTING RUSTY	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT, FRONT CHASSIS COVERED	الارضية
01.F Bumper	MISALIGN PORTION CRACKED,RIGHT SIDE WASHER COVER MISSING	دعامية
01.G Windshield	REAR CURTAIN PORTION DAMAGED	زجاج
01.H Bonnet	REPAINTED PORTION REPAIRED,STAY SHOCK NOT WORKING	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK,	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CRACKED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK REFITTED, GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX PORTION LOOSE ,INTERIOR PARTS GETTING RUSTY	اخري
09.B Mirror	CENTER VIEW MIRROR BACK COVER PART MISSING	المرايا
09.C AC Condition	OK,GRILL,PORTION DAMAGED	المكيف
09.D Dash Board	LEATHER REPLACED PORTION DAMAGED,LOOSE	لوحة القياده
09.E Sun Visor	LEFT SIDE PORTION LOOSE	حاجب الشمس
09.F Odometer reading	CLUSTER DISPLAY PORTION FADED	قراءة عداد المسافات
09.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.H Steering Wheel and control buttons	HORN NOT WORKING, SWITCH PORTION FADED	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	KNOB,DUST COVER WORN OUT,GEAR LOCK COVER MISSING	ذراع نقل السرعات
09.J Engine Start Button	REMOTE PORTION DAMAGED	زر تشغيل المحرك
10 Battery Condition		حالة البطارية
10.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.