

Queue Number 2865905

Transaction Date 14 Oct 2026, 16:56:29

Site Name
840 - Emirates AuctionsTransaction Number
18958525 (CC10009) (CC10012)

Vehicle Details

Chassis Number	LGWFF8A68L*****
Specification	GCC Specification
Make	Haval
Model	H9
Model Year	2020
Color	Silver
Mileage	67776 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.B Doors	FRONT LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.C Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
02 Chassis Condition		الشاسي
02.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT ADJUSTMENT NOT WORKING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	DELAY SHIFTING SOMETIME MAJOR JERKING/ PARTS REFITTED GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED , CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED , CRACK	الاطار الخلفي

Condition	Remarks	الحالة
07 Lights		الاضاءة
07.A Head Light	LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Indicator & Hazard light	HAZARD LIGHT FUALT	الاشارات
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	NOT WORKING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY WEAK	دواسة الفرامل
08.B Other	ABS FUALT	اخرى
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR REFITTED , (WATER FLOODED) ELECTRIC FAULT	اخرى
09.B AC Condition	NOT WORKING	المكيف
09.C Power Window Switch And Glass	FRONT RIGHT SIDE , REAR BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
09.D Dash Board	WORN OUT	لوحة القيادة
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Sunroof	NOT WORKING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae