



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 Nov 2022, 11:15:46
Transaction Number	27566893 (CC10009)	Queue Number	621606



Chassis Number	WAURGBFD2EN001425
Engine Number	
Vehicle Class	Car
Manufacturer	Audi
Model	A8
Model Year	2014
Color	Black
Mileage	109403 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Spare Tire & Tools	TIRE MISSING	الاطار الاحتياطي و العدة
01.B Front Tyre	BOTH SIDE 2022	الاطار الامامي
01.C Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
02 Chassis Condition		الشاسي
02.A Chassis	CHECKED VISIBLE AREA ONLY /OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	MOUNT CRACK	كرسي
03.B Smoke	BLACK SMOKE	دخان
03.C Visual Engine Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة المحرك النظري
04 Suspension System		ممتص الصدمات
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
05 Interior Condition		الحاله الداخليه
05.A Roof Ceiling	LOOSE	بطانه السقف
05.B Audio	NOT WORKING	صوتيات

DEFECT	REMARKS	
05.C AC Condition	OK	المكيف
06 Body		جسم المركبة
06.A Floor	UNDER FLOOR CHASSIS COVERED , MUDDY CHECKED VISIBLE AREA ONLY	الارضية
06.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
06.C Sign of side accident		وجود مؤشر لحادث في الجانب
06.D Bonnet	REPAIRED,REPAINTED & REFITTED	غطاء المحرك
06.E Fenders	PORTION REPAIRED,REPAINTED & FRONT REFITTED	مدكار
06.F Bumper	MISALIGN, FRONT ASSEMBLY REFITTED	دعامية
06.G Sign of front accident		وجود مؤشر لحادث في المقدمة
06.H Doors	FRONT LEFT SIDE , REAR RIGHT SIDE PORTION REPAIRED REPAINTED	أبواب
06.I Other	FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REFITTED	اخرى
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	JERKING, REFITTED	حالة الجير النظرى
08.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
08.C Road Test	NOT CHECK	فحص علي الطريق
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.