



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Oct 2021, 17:42:44</b>
Transaction Number	<b>92636744 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1GCNK9E03BZ114859</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Silverado</b>
Model Year	<b>2011</b>
Color	<b>Red</b>
Mileage	<b>0 N/A</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT LEFT SIDE REPAIRED, REPAINTED & RIGHT SIDE REPAINTED	مدكار
01.B Paint	PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	LEFT SIDE REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	REPAINTED	دعامية
01.F Bonnet	REPAIRED, REPAINTED	غطاء المحرك
01.G Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT REPAIRED	اخرى
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Other	COVER PORTION DAMAGED	اخرى
<b>03 Wipers and Arms</b>		<b>المساحات</b>
03.A Other	WORN OUT	اخرى
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2013/2020 CRACKED & EXPIRED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018/2019	الاطار الخلفي
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Head Light	OK	الاضاءة الرئيسية

DEFECT	REMARKS	
05.B Other	OK	اخرى
05.C Tail Light	TOP ROOF LIGHT COVER DAMAGED	الانارة
05.D Warning Light	SRS ON	ضوء تحذير
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED & GETTING RUSTY	ازرع
06.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Steering Boot	BOOT LEAKING	ربلة المقود
07.B Rack Pinion	OIL LEAK	مسطرة المقود
07.C Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
<b>08 Interior Condition</b>		<b>الاجزاء الداخلية</b>
08.A Other	OK	اخرى
08.B Mirror	OK	المرايا
08.C AC Condition	OK	المكيف
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Other	OK	اخرى
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	CHASSIS FRAME COMPLETELY RUST PROOFED & RUSTY	الشاسيه
<b>11 Transmission Condition</b>		<b>الجير</b>
11.A Gear Box	OK	الجير
11.B Gear Box Mount	BUSHES CRACKED	كرسي الجير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.