

Queue Number 2899407

Transaction Date 23 Oct 2026, 15:28:27

Site Name
840 - Emirates AuctionsTransaction Number
45512248 (CC10013) (CC10011)

Vehicle Details

Chassis Number	JN8AY2NYXG*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2016
Color	Grey
Mileage	125651 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	REAR LEFT SIDE REFITTED,RIGHT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DIRTY	الارضية
01.F Bumper	MISALIGN SCRATCHES	دعامية
01.G Windshield	PORTION CRACK,COWL PANEL COVER PART MISSING	زجاج
01.H Bonnet	STAY SHOCK NOT WORKING,REFITTED	غطاء المحرك
01.I Trunk	REAR SWITCH DAMAGED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME DIRTY GETTING RUSTY	الشاسيه
--------------	-----------------------------------	---------

03 Engine Condition

المحرك

03.A Other	INNER COMPARTMENT ELECTRIC WIRE WORN OUT	اخرى
03.B Engine Visual Condition	OIL LEAK DRIPPING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION CRACK WORN OUT	حالة المقاعد
---------------------	------------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2025,RIGHT 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
07.C Ball Joint	BOOT DRY CRACK	مفصل كروي
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING	المرايا
08.C AC Condition	OK	المكيف
08.D Power Window Switch And Glass	SWITCH PORTION GETTING WORN OUT	مفتاح النافذه و الزجاج
08.E Dash Board	PORTION MELTED WORN OUT	لوحة القيادة
08.F Sun Visor	RIGHT SIDE MIRROR COVER LOOSE	حاجب الشمس
08.G Door Panel	PORTION DAMAGED	لوحة بطانة الباب
08.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae