CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3013151
Transaction Date	20 Nov 2026, 16:53:45
Site Name	840 - Emirates Auctions
Transaction Number	80906247 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WF0FC9KH9H*******
Specification	GCC Specification
Make	Ford
Model	Focus
Model Year	2017
Color	Black
Mileage	126528 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED(BODY KIT MODIFIED)	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GTETING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION MINOR DENT	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Other	INTAKE AIR PIPE FILTER MODIFIED	اخري
03.C Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Exhaust System		نظام العادم
04.A Other	SYSTEM MODIFIED	اخري
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الخلفي
06.C Rims Condition	EXTRA SPACER / HUB COVER MISSING	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخري
08.B Mirror	LEFT SIDE INDICATOR LIGHT COVER DAMAGED	المرايا
08.C AC Condition	OK	المكيف
08.D Roof Light	SUNGLASSES BOX PANEL PART MISSING	أنارة السقف
08.E Power Window Switch And Glass	BOTH SIDE QUARTER GLASS BEADING DAMAGED	مفتاح النافذه و الزجاج
08.F Sun Visor	LEFT SIDE MIRROR COVER MISSING	حاجب الشمس
08.G Door Panel	LEATHER PORTION LOOSE WORN OUT	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae