





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20091756	Plate Category	: PRIVATE
Transaction Date	: 30 JUN 2020 10:19:02	Plate Number	: 270051 EA
Queue Number	: 190834	Import Doc. Ref.	:
Chassis Number	: JN1AZ4EH9JM270051	Manufacturer/Model	: NISSAN/Z370
Engine Number	:	Model Year	: 2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.04 - Fenders		المدكار
05.05 - Bumpers		الدعامية
05.08 - Chassis (Frame)		الشاصية
05.12 - Side Safety Frame		الواقيات الجانبية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.23 - Air Bag Damaged		المخذة الهوائية لا تعمل
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted		أثر صينغ في المركبة
		BONNET & FRONT LEFT FENDER REPLACED
		FRONT BUMPER REPLACED & BUMPER SUPPORT FRAME BEND (LEFT SIDE)
		FRONT LEFT SIDE FRAME MEMBER END BULGED
		BULKHEAD REFITTED
		TIRES 2017 & 2018
		FRONT SUSPENSION REFITTED
		80748 KM
		BOTH SIDE CURTAIN AIR BAG DEPLOYED & CUT
		AIR BAG LIGHT ON
		REPAINTED (EXCEPT ROOF & REAR RIGHT FENDER)

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20091756	Plate Category	: PRIVATE
Transaction Date	: 30 JUN 2020 10:19:02	Plate Number	: 270051 EA
Queue Number	: 190834	Import Doc. Ref.	:
Chassis Number	: JN1AZ4EH9JM270051	Manufacturer/Model	: NISSAN/Z370
Engine Number	:	Model Year	: 2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Test Certificate



PASS

Possession Certificate : 63208994	
Chassis No :	JN1AZ4EH9JM270051
Vehicle Make :	NISSAN
Vehicle Model :	350Z
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	80750 Kms.
Origin : Japan	Model Year : 2018
Gear Type : --	Engine Size : 3500 CC
Engine No : VQ3782292...	Horse Power : 332
Axles No : 2	Cylinders : 6
No Of Doors : 2	No Of Seats : 2
G. V. W. : 1798 Kgs.	Empty Weight : 1553 Kgs.

Certificate Number :	5-TAS-2020-12087571
Inspection Date :	02-07-2020
Certificate Print Date :	02-07-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	16 min 31 sec
Appointment Ref Number :	--
Start Time : 12:00	End Time : 12:17
Lane : 01	Token No. : 4
Attempt : 1	Prints No : 1

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

16150 KM Distance per year	1662 L Fuel consumed per year	2693 AED Fuel cost per year	4.0 ton Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 5 %	Service brake imbalance on rear axle 4 %	Parking brake imbalance between LHS and RHS 35 %	Vehicle on Petrol CO Reading 0.44 %
Vehicle on Petrol HC Reading 138 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Vehicle Model - Registration Incorrect Model - Does Not Require Document	350Z	370Z	
Engine Size Discrepancy in Engine Size	3500	3700	

Inspection Remarks: FRONT LEFT SIDE FRAME MEMBER END BULGED & BUMPER SUPPORT DENT