



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Aug 2022, 18:00:59
Transaction Number	82777048 (CC10006)	Queue Number	312309



Chassis Number	WDCYR70F99X178672
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	G 55
Model Year	2009
Color	Black
Mileage	294534 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Roof	ROOF&ROOF RAIL&REAR DOOR PILLAR CUT FOR HARD TOP MODIFIED	السقف
01.B Paint	BODY TOTALY REPAINTED, REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.C Sign of front accident		وجود مؤشر لحادث في المقدمة
01.D Bumper	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.FRONT BUMPER FRAME CUT ,REWELDED.	دعامية
01.E Floor	FRONT BODY MOUNT REPAIRED.	الارضية
02 Interior Condition		الحاله الداخليه
02.A Roof Ceiling	PORTION LOOSE	بطانه السقف
02.B AC Condition	OK	المكيف
02.C Power Window Switch	REAR RIGHT SIDE NOT WORKING	مفتاح النافذه
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Propeller Shaft	BOOT CUT	ناقل الحركة
03.C Visual Gear Box Condition	REFITTED SIGN OF OILLEAK	حالة الجير النظري

DEFECT	REMARKS	
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
05 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED OIL WET	حالة المحرك النظري
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED,	ازرع
08 Steering Condition		المقود
08.A Steering Oil	OIL LEAK	زيت المقود
09 Exhaust System		نظام العادم
09.A Other	REWLDED	اخرى
10 Chassis Condition		الشاسي
10.A Chassis	FRONT LEFT CHASSIS OUTER HEATED REPAIRED.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	Y 68741 Dubai Private
Chassis No :	WDCYR70F99X178672
Vehicle Make :	MERCEDES
Vehicle Model :	G55
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	294578 Kms.
Origin : Australia	Model Year : 2009
Gear Type : Automatic	Engine Size : 4700 CC
Engine No : NONE	Horse 507
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 2500 Kgs.	Empty 2000 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17683496
Inspection Date :	21-09-2022
Certificate Print Date :	21-09-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	12 min 35 sec
Appointment Ref Number :	--
Start Time : 15:03	End Time : 15:16
Lane : 02	Token No. : 60
Attempt : 2	Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)

13053 KM	1344 L	4476 AED	3.3 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	4700	5500	

Inspection Remarks: HAVE RTA APPROVAL FOR BODY MODIFICATION

Payment Details

Inspection Performed by 34600	Payment Method Cash	Transaction Number 17683496	Service Fees AED 70 Collected on 21/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

