

Queue Number 2742566

Transaction Date 11 Sep 2026, 11:14:17

Site Name
840 - Emirates AuctionsTransaction Number
90111753 (CC10021) (CC10011)

Vehicle Details

Chassis Number	SCBBM5ZG3P*****
Specification	GCC Specification
Make	Bentley
Model	Flying Spur
Model Year	2023
Color	--
Mileage	10472 Km
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY TOTALLY PROTECTION STICKER PAINT NOT CHECK,MINOR SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR,ENGINE,GEAR COVERED,CHECKED VISIBLE AREA ONLY	الارضية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Vehicle Color	GOLD	لون المركبة
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETE COVERED,CHECKED VISIBE AREA ONLY / OK	الشاسيه
02.B Other	REMOVE BOTH SIDE & UNDERNEATH COVER,FOR FULL INSPECTION	اخرى
03 Engine Condition		المحرك
03.A Engine Visual Condition	VISUAL OK	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	VISUAL OK	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
05.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
06 Interior Condition		الحالة الداخلية
06.A AC Condition	OK	المكيف
06.B Sunroof	CURTAIN LOOSE	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae