



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	10 Oct 2021, 17:42:55
Transaction Number	98333534 (CC10006)	Queue Number	312309



Chassis Number	JN6FE54S15X418910
Engine Number	
Vehicle Class	Heavy
Manufacturer	Nissan
Model	Urvan
Model Year	2005
Color	White
Mileage	0 N/A

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAIRED&REPAINTED&RUSTY PORTION	الصبغ
01.C Doors	REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, FLOORING , CHASSIS GETTING RUSTY	صدأ
01.E Floor	QUATER PANEL,REAR & FRONT WHEEL HOUSING , FLOORING RUSTY WEAK , HOLE	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	REPAIRED, REPAINTED & RUSTY	السقف
01.H Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.I Other	FRONT FENDER FRAME, BUMPER FRAME & CROSSMEMBER REPAIRED	اخرى
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS RUSTY & PORTION RUST PROOFED	الشاسيه
03 Seats Condition		المقاعد
03.A Other	COVER PORTION DAMAGED	اخرى
04 Transmission Condition		الجير
04.A Gear Box	OIL LEAK	الجير
04.B Gear Box Mount	BUSHES CRACKED	كرسي الجير

DEFECT	REMARKS	
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2017 CRACKED & EPAIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2017 CRACKED & EPAIRED	الاطار الخلفي
06 Wipers and Arms		المساحات
06.A Other	WORN OUT	اخرى
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
07.B Other	OK	اخرى
08 Brake Condition		الفرامل
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
09.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
09.C Suspension Subframe	SUSPENTION SUB FRAME & CROSSMEMBER GETTING RUSTY	
09.D Shock Absorber	LEAK & WEAK	ممتص الصدمات
10 Steering Condition		المقود
10.A Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
10.B Other	STABILIZER LINK BUSHES DRY CRACKED	اخرى
11 Interior Condition		الاجزاء الداخلية
11.A Other	DASH BOARD CRACKED , SUN ROOF RIGHT SIDE MISSING	اخرى
11.B Mirror	OK	المرايا
11.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.