

TEST CERTIFICATE

Site Number
Transaction Number

03.A Front Tyre

03.B Rear Tyre

04 Transmission Condition

840-Emirates Auctions 36856241 (CC10006) Transaction Date

29 Nov 2022, 13:07:26

Queue Number

632629



Chassis Number SALVA1BG6CH603794

Engine Number

Vehicle Class Car

Manufacturer Range Rover

Model Evoque

Model Year 2012

Color White

Mileage 46993 Km

Fuel Type

No. Of Cylinders

Specification

GCC Specification

الاطار الامامي

الاطار الخلفى

الجير

Petrol

DEFECT REMARKS

O1 Body		جسم المركبة
01.A Fenders	FRONT FENDERS FABIERS & REFITTED	مدكار
01.B Sign of front accident		وجود مؤشر لحادث في المقدمة
01.C Other	FRONT FENDER FRAME, RADITOR SUPPORT , BULK HEAD,BUMPER FRAME REPAIRED	اخري
01.D Bonnet	REFITTED	غطاء المحرك
01.E Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.F Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES	الصبغ
01.G Floor	UNDER FLOOR PORTION COVERED,CHECKED VISIBLE AREA OK	الارضية
02 Interior Condition		الحاله الداخليه
02.A AC Condition	ОК	المكيف
03 Tires and Rims Condition		الاطارات

BOTH SIDE 2020

BOTH SIDE 2020

DEFECT	REMARKS	
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	REFITTED, MINOR LEAK	حالة الجير النظرى
05 Chassis Condition		الشاصي
05.A Chassis	FRONT LEFT SIDE CHASSIS OUTER SKIRT REPAIRED	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED, SIGN OF LEAK	حالة المحرك النظرى
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate

PASS











Certificate Number: 5-TAS-2022-18220619 Inspection Date: 30-11-2022 Certificate Print Date : 30-11-2022 Services: Registration Test Vehicle Testing Partner: Tasieel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 6 min 33 sec **Appointment Ref** Number: Start 17:06 End Time: 17:13 Time: Token No.: 251 Lane: 01 Prints No: 1 Attempt: 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)



Distance per

year





2353 AED 1.7
Fuel cost per Carbon
year per

1.7 ton Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 3 %

Service brake imbalance on rear axle 24 %


Parking brake imbalance between LHS and RHS 59 % Vehicle on Petrol CO Reading 0%

Vehicle on Petrol HC Reading

9 PPM VOL

Inspection Remarks:

BULKHEAD FENDER FRAME RADIATOR SUPPORT REPAIRED / FRONT LEFT SIDE MEMBER FRAME OUTER OLD REPAIRED, .



Payment Details

Inspection Performed by 31339

Parking Slot No

Payment Method
Cash

Service Name Registration Test **Transaction Number** 18220619

Attempt 1

Service Fees

AED 170 Collected on 30/11/2022

Received by Shawkat Mohamed Samir

- 🚯 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
 ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أُصدِرَت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
 30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.