CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2426607
Transaction Date	01 Jun 2026, 16:00:08
Site Name	840 - Emirates Auctions
Transaction Number	11382796 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WD4WA5A69C*******
Specification	GCC Specification
Make	Mercedes
Model	Viano
Model Year	2012
Color	Black
Mileage	67477 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED ,MINOR DENTS SCRATCHES ,	الصبغ
01.B Doors	RIGHT SIDE REPAINTED ,PORTION REPAIRED.	أبواب
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA .	الارضية
01.E Bumper	MISALIGN ,SCRATCHES .	دعامية
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA,PORTION DENT ,GETTING RUSTY. CLEAN CHASSIS FOR INSPECTION.	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY.	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DIRTY PORTION LOOSE.	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY.	الحالة النظريه للجير
06 Tires and Rims Condition		**الاطارات**

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2020 EXPIRED CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 EXPIRED CRACKED WORN OUT .	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CRACKED.	ربلة المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR CONDITION DIRTY ,SIGN OF FLOODED.	اخري
10.B Mirror	LEFT SIDE DAMAGED .	المرايا
10.C Dash Board	WORN OUT PORTION LOOSE,FADED.	لوحة القياده
10.D Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae