CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2953773
Transaction Date	12 Nov 2026, 10:26:03
Site Name	840 - Emirates Auctions
Transaction Number	13213686 (CC10008) (CC10011)



Vehicle Details

Chassis Number	5N1AL0MM7E*******
Specification	GCC Specification
Make	Infiniti
Model	QX60
Model Year	2014
Color	Silver
Mileage	111841 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH,REAR LEFT SIDE REPANTED PORTION REPAIRED,FRONT LEFT REFITTED MISALIGN STRIP MISSING	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED,FRONT LEFT SIDE REFITTED	أبواب
01.D Bumper	MISALIGN PORTION CRACK	دعامية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Pillars	LEFT SIDE A/PILLAR OUTER PANEL PORTION REPAIRED REPAINTED	القوائم
01.G Trunk	MISALIGN,NOT OPEN	صندوق
01.H Sign of front accident	BUMPER FRAME,FENDER INNER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA /OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	STARTING HAVE ISSUE SOME TIME ENGINE NOT START	اخري
03.B Engine Visual Condition	OIL LEAK ,REFITTED,ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CRACK WORN OUT,FRONT RIGHT SEAT ADJUSTMENT SWITCH PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK ,REFITTED,DELAY SHIFTING ,POOR POWER	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNNIG LIGHT SHOW IN DISPLAY	ضوء تحذير
07.C Fog light	LEFT SIDE CHROME MISSING	كشاف الضباب
08 Interior Condition		الحاله الداخليه
08.A Other	(INTERIOR PARTS RUSTY , SIGN OF FLOODED, CENTER CONSOLE BOX COVER PORTION DAMAGED,PANEL PORTION CRACK,CONTROL SWITCH PORTION DAMAGED , CUP HOLDER COVER NOT CLOSE	اخري
08.B Mirror	LEFT SIDE AUTO FOLDING NOT WORKING,RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
08.C AC Condition	NO COOLING	المكيف
08.D Roof Light	FRONT NOT WORKING	أنارة السقف
08.E Audio	SCREEN PORTION FADED	صوتيات
08.F Dash Board	PORTION WORN OUT	لوحة القياده
08.G Roof Ceiling	PORTION DAMAGED WORN OUT	بطانه السقف
08.H Door Panel	PORTION DAMAGED WORN OUT	لوحة بطانة الباب
08.I Air Bag	LEFT SIDE DAMAGED	وسائد هوائية
08.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.K Sunroof	REAR CURTAIN NOT WORKING PROPERLY LOOSE	فتحت سقف
08.L Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
08.M Engine Start Button	FADED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae