



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>16 Oct 2021, 16:53:26</b>
Transaction Number	<b>70160118 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WGY60353347</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Patrol</b>
Model Year	<b>1996</b>
Color	<b>White</b>
Mileage	<b>0 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Chassis Condition</b>		<b>الشاسي</b>
01.A Chassis Number	STICKER MISSING	رقم القاعدة
01.B Chassis	CHASSIS FRAME REPAIRED & DENT, BULDGE	الشاسيه
01.C Other	CHASSIS FRAME COMPLETELY THICK RUST PROOFED & PAINT	اخرى
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY TOTALY REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
02.B Fenders	FRONT BOTH SIDE REPAIRED & REFITTED	مدكار
02.C Floor	UNDER FLOOR RUSTY REPAIRED	الارضية
02.D Pillars	RUSTY REPAIRED	القوائم
02.E Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD & CROSSMEMBER REPAIRED OLD	اخرى
02.F Bonnet	STAND MISSING	غطاء المحرك
<b>03 Steering Condition</b>		<b>المقود</b>
03.A Steering Box	BOTH SIDE ROMANO LEAKING	جهاز المقود
03.B Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات

DEFECT	REMARKS	
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	RIGHT SIDE CONTROL ARM MOUNT REPAIRED	أزرع
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Belt	REAR BOTH SIDE MISSING	حزام الأمان
<b>06 Exhaust System</b>		<b>نظام العادم</b>
06.A Modification	MODIFIED	تعديلات
06.B Other	WELDED & REPAIRED	اخرى
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Front Tyre	BOTH 2018	الاطار الامامي
07.B Rear Tyre	BOTH 2018	الاطار الخلفي
<b>08 Brake Condition</b>		<b>الفرامل</b>
08.A Disc&Drum	GETTING RUSTY	دسك ووطنابير الفرامل
<b>09 Interior Condition</b>		<b>الحالة الداخليه</b>
09.A AC Condition	NOT WORKING	المكيف
09.B Mirror	OK	المرايا
09.C Audio	FRONT LEFT SIDE SPECKER LOSE	صوتيات
<b>10 Engine Condition</b>		<b>المحرك</b>
10.A Engine Condition	OK	حالة المحرك
<b>11 Transmission Condition</b>		<b>الجير</b>
11.A Gear Box	OK	الجير
<b>12 Wipers and Arms</b>		<b>المساحات</b>
12.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



PENDING

Plate Details :	10 75341 Abu Dhabi Private	
Chassis No :	WGY60353347	
Vehicle Make :	NISSAN	
Vehicle Model :	PATROL	
Vehicle Class :	Light Vehicle	
Body Type :	STATION	
Fuel :	Benzene	
Color :	White	
Drive Direction :	--	
Dimensions : (H x W x L) :	-- x -- x --	
Current Odometer :	267715 Kms.	
Origin :	Japan	Model Year : 1996
Gear Type :	--	Engine Size : 2700 CC
Engine No :	116758	Horse Power : --
Axles No :	2	Cylinders : 6
No Of Doors :	4	No Of Seats : 7
G. V. W. :	1800 Kgs.	Empty Weight : 1400 Kgs.

Not allowed to be used as an official Doc

**▲ Please communicate with the inspection supervisor at the same testing center in order to complete your transaction**

Certificate Number :	5-TAS-2021-15274148	
Inspection Date :	19-10-2021	
Certificate Print Date :	19-10-2021	
Services :	Registration Test	
Vehicle Testing Partner :	Tasjeel	
Vehicle Testing Center :	Tasjeel Al Aweer	
Total Time Taken :	20 min 20 sec	
Appointment Ref Number :	--	
Start Time :	15:34	End Time : 15:55
Lane :	03	Token No. : 171
Attempt :	1	Prints No : 1

## Parameter Readings

Service brake imbalance on front axle  
28 %

Service brake imbalance on rear axle  
13 %

Parking brake imbalance between LHS and RHS  
15 %

Vehicle on Petrol CO Reading  
1.63 %

Vehicle on Petrol HC Reading  
87 PPM VOL

## Inspection Findings

Defects	Issue	Severity
Stop lamps	Bulb busted	Major

## Pending Defect for Fixing

Issue
Stop lamps
Bulb busted

Inspection result will be fail automatically in case the pending defects were not repaired within 4 calendar days

## Inspection Remarks:

RUNNING BOARD RUSTY REPAIRED..CHASSIS FRAME RUST PROOFED.FRONT RIGHT SIDE CHASSIS REPAIRED// FRONT LEFT SIDE CHASSIS BULGED, F BULK HEAD, FENDER FRAME, RADIATOR SUPPORT REPAIRED, REAR QUARTER PANEL REPAIRED

## Payment Details

Inspection Performed by 37084	Payment Method Cash	Transaction Number 15274148	Service Fees AED 170 Collected on 19/10/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

