CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2934028 |
| Transaction Date | 05 Nov 2026, 10:52:33 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 11832918 (CC10026) (CC10026) |



**Vehicle Details**

| | |
|---|---|
| Chassis Number | JTFHX02PX6******* |
| Specification | GCC Specification |
| Make | Toyota |
| Model | Hiace |
| Model Year | 2006 |
| Color | White |
| Mileage | 370751 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Paint | BODY REPAINTED PORTION REPAIRED , DENTS SCRATCHES , PORTION RUSTY | الصبغ |
| 01.B Rusty | UNDER FLOOR PARTS RUSTY HOLE , WEAK | صدأ |
| 01.C Floor | FLOOR CUT RUSTY HOLE , WEAK | الارضية |
| 01.D Bumper | MISALIGN, PORTION DAMAGE | دعامية |
| 01.E Roof | NEED TO REMOVE ROOF COVER FOR RE INSPECTION | السقف |
| 01.F Pillars | BOTH SIDE B/PILLAR ROCKER PANEL REPAIRED | القوائم |
| 01.G Other | BODY PORTION CUT REWELD RUSTY BULGED HOLE REPAIRED | اخري |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis Extension | REAR BOTH SIDE CHASSIS EXTENSION RUSTY REPAIRED , DENT | تمديدات الشاسي |
| 02.B Chassis | CHASSIS GETTING RUSTY , FRONT RIGHT SIDE CHASIS END REPAIRED , DENT | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |
| 04.A Seat Condition | PORTION WORN OUT , EXTRA COVER , REAR SEATS MISSING | حالة المقاعد |
| **05 Transmission Condition** | | الجير |

| Condition | Remarks | الحالة |
|---|---|---|
| 05.A Gear Box Visual Condition | NOT CHECK , REFITTED PARTS GETIING RUSTY | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECK | فحص علي الطريق |
| **06 Tires and Rims Condition** | | **الاطارات** |
| 06.A Front Tyre | BOTH SIDE 2025 | الاطار الامامي |
| 06.B Rear Tyre | BOTH SIDE 2025 , LEFT SIDE GETTING WORN OUT | الاطار الخلفي |
| **07 Lights** | | **الاضاءة** |
| 07.A Head Light | LENS FADED , ALL LIGHT NOT CHECK | الاضاءة الرئيسية |
| 07.B Tail Light | BOTH SIDE CRACK | الضوء الخلفي |
| **08 Brake Condition** | | **الفرامل** |
| 08.A Disc&Drum | RUSTY | دسك وطنابير الفرامل |
| **09 Suspension System** | | **ممتص الصدمات** |
| 09.A Arms | BUSHES CRACK | ازرع |
| 09.B Stabilizer Bar And Link Rod | BOOT CRACK | عمود التوازن و مثبت عمود التوازن |
| **10 Interior Condition** | | **الحاله الداخليه** |
| 10.A Other | INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED | اخري |
| 10.B Mirror | CENTER MIRROR DAMAGE | المرايا |
| 10.C AC Condition | NOT CHECK , GRILL DAMAGE | المكيف |
| 10.D Dash Board | WORN OUT , GLOVE BOX LOCK NOT WORKING | لوحة القياده |
| 10.E Roof Ceiling | DAMAGE | بطانه السقف |
| 10.F Door Panel | WORN OUT | لوحة بطانة الباب |
| 10.G Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 10.H Gear Shifting Lever | KNOB WORN OUT | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae