CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934004
Transaction Date	04 Nov 2026, 14:28:01
Site Name	840 - Emirates Auctions
Transaction Number	96920094 (CC10010) (CC10010)



Vehicle Details

Chassis Number	VF14SRAB9H*******
Specification	GCC Specification
Make	Renault
Model	Symbol
Model Year	2017
Color	Brown
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT & REAR REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	PORTION REPAINTED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAIRED REPAINTED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME BEND,BULKHEAD,RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED OILY MUDDY PORTION MINOR DENT CHECKED ONLY VISIBLE AREA .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY.	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED , ,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CUT .	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
09.B Mirror	COVER MISSING	المرايا
09.C AC Condition	NOT CHECKED.	المكيف
09.D Dash Board	PORTION LOOSE	لوحة القياده
09.E Odometer reading	NOT CHECKED.	قراءة عداد المسافات
09.F Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN O UT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae