CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906056
Transaction Date	26 Oct 2026, 12:51:14
Site Name	840 - Emirates Auctions
Transaction Number	38625801 (CC10021) (CC10021)



Vehicle Details

Chassis Number	MMDAF26J8L*******
Specification	GCC Specification
Make	Mitsubishi
Model	Attrage
Model Year	2020
Color	Silver
Mileage	119061 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	3

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , GETTING RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE FIXS BY SCREW	دعامية
01.E Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	REAR LEFT SIDE CHASSIS EXTENSION REPAIRED , BEND	الشاسيه
03 Engine Condition		المحرك
03.A Mount	UPPER MOUNT BUSHES CUT	كرسي
03.B Engine Visual Condition	PARTS GETTING RUSTY , MINOR OIL LEAK , SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Brake Condition		الفرامل
06.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	NOT COOLING	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القياده
08.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
08.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae