

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 73648923 (CC10006) Transaction Date

28 Sep 2022, 14:01:22

Queue Number

597250



Chassis Number NLAFC5630LW015427

Engine Number

Vehicle Class Car

Manufacturer Honda

Model Civic

Model Year 2020

Color Grey

Mileage 47575 Km Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

 O1 Body

O1.A Fenders FRONT LEFT SIDE PORTION REPAIRED, REPAINTED

O1.B Doors FRONT RIGHT SIDE REPAINTED

O1.C Bumper MISALIGN & PORTION DAMAGED

وجود مؤشر لحادث في الجانب وجود مؤشر لحادث في الجانب

O1.E Paint PORTION REPAIRED, REPAINTED & DENTS, DENTS,

SCRATCHES ON BODY

O2 Interior Condition

 O2.A Audio
 DISPLAY DAMAGED

 O2.B AC Condition
 NOT CHECKED

الاطارات 03 Tires and Rims Condition

03.A Rear Tyre BOTH SIDE 2020 الاطار الخلفي 03.B Front Tyre BOTH SIDE 2020& RIGHT SIDE PUNCHER

المحرك Uhacle

04.A Visual Engine Condition ENGINE NOT START ALL SYSTEM NOT CHECK, MINOR OIL LEAK

حالة المحرك النظرى

الصبغ

O5 Lights

DEFECT	REMARKS	
05.A Tail Light	REAR LEFT SIDE DAMAGED	الانارة
06 Chassis Condition		الشاصي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	NOT CHECK	حالة الجير النظرى
07.B Road Test	NOT CHECK	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.