CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3004589
Transaction Date	18 Nov 2026, 13:15:25
Site Name	840 - Emirates Auctions
Transaction Number	53464958 (CC10009) (CC10019)



Vehicle Details

Chassis Number	3GYFNFEY9A*******
Specification	GCC Specification
Make	Cadillac
Model	SRX
Model Year	2010
Color	Red
Mileage	198804 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED EXCEPT ROOF MINOR DENT SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR PORTION DENT	الارضية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Trunk	REFITTED	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS COVERED PORTTON MINOR DENT OK	الشاسيه
02.B Other	REMOVE FRONT BOTH SIDE UNDER CHASSISFOR RECHECK PROPERLY	اخري
02.C Chassis Number	CHECKED ONLY ON STICKER WINDSHIELD NUMBER DIRTY SUSPECT REFITTED	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT SIDE COVER PORTION DAMAGED.LOOSE	حالة المقاعد
05 Exhaust System		**نظام العادم**

Condition	Remarks	الحالة
05.A Catalytic Converter	CUT REWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OIL WET REFITTED GETTING RUSTY, DELAY SHIFTTING	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CRACKED	ازرع
10 Steering Condition		المقود
10.A Steering Oil	MINOR OIL LEAK	زيت المقود
10.B Steering Boot	BOTH SIDE BOOT MISSING	ربلة المقود
10.C Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INETRIOR PARTS GETTING RUSTY SIGN OF FLOODED & CENTER CONSOLE BOX COVER WORN OUT	اخري
11.B AC Condition	OK	المكيف
11.C Audio	FOLDING NOT WORKING ,COVER LOOSE	صوتيات
11.D Sun Visor	LEFT SIDE MIRROR CRACKED,COVER MISSING ,RIGHT SIDE COVER DAMAGED	حاجب الشمس
11.E Door Panel	PORTION DAMAGED,LOOSE	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Sunroof	CURTAIN DAMAGED,MISSING	فتحت سقف
11.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae