CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906095
Transaction Date	30 Oct 2026, 14:53:45
Site Name	840 - Emirates Auctions
Transaction Number	40328484 (CC10026) (CC10021)



Vehicle Details

Chassis Number	3GYFNFEY6A*******
Specification	GCC Specification
Make	Cadillac
Model	SRX
Model Year	2010
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED, PARTS REFITTED MINOR OIL LEAK . PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DAMAGE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED, REFITTED MINOR OIL LEAK PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي

Condition	Remarks	الحالة
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE CRACK	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	BOTH SIDE CRACK	
09.B Arms	BUSHES CRACK	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX PORTION WORN OUT	اخري
10.B AC Condition	NOT CHECK	المكيف
10.C Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae