



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>09 May 2022, 15:19:40</b> |
| Transaction Number | <b>56695435 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>WPOZZZ98ZW3601123</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Porsche</b>           |
| Model            | <b>Boxster</b>           |
| Model Year       | <b>1997</b>              |
| Color            | <b>White</b>             |
| Mileage          | <b>124067 Miles</b>      |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>6</b>                 |
| Specification    | <b>European Imported</b> |

| DEFECT                             | REMARKS   |                     |
|------------------------------------|---|---------------------|
| <b>01 Body</b>                     |   | <b>جسم المركبة</b>  |
| 01.A Fenders                       | FRONT BOTH SIDE REPAINTED & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED | مدكار               |
| 01.B Bonnet                        | SHOCK WEAK & REPAINTED  | غطاء المحرك         |
| 01.C Doors                         | REPAINTED & LEFT SIDE REFITTED  | أبواب               |
| 01.D Paint                         | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES            | الصبغ               |
| 01.E Trunk                         | REPAINTED & REFITTED  | صندوق               |
| 01.F Bumper                        | MISALIGN  | دعامية              |
| <b>02 Tires and Rims Condition</b> |   | <b>الاطارات</b>     |
| 02.A Front Tyre                    | BOTH SIDE 2020  | الاطار الامامي      |
| 02.B Rear Tyre                     | BOTH SIDE 2019  | الاطار الخلفي       |
| <b>03 Lights</b>                   |   | <b>الاضاءة</b>      |
| 03.A Tail Light                    | RIGHT SIDE CRACKED  | الانارة             |
| <b>04 Suspension System</b>        |   | <b>ممتص الصدمات</b> |
| 04.A Arms                          | LOWER ARM BUSHES CRACKED  | ازرع                |
| 04.B Shock Absorber                | OIL LEAK  | ممتص الصدمات        |

| DEFECT                                  | REMARKS                                    |                            |
|---|--|----------------------------|
| 04.C Ball Joint                         | BOOT CUT                                   | مفصل كروي                  |
| <b>05 Steering Condition</b>            |  | <b>المقود</b>              |
| 05.A Axle                               | BOOT CUT                                   | اكسلات                     |
| <b>06 Chassis Condition</b>             |  | <b>الشاصي</b>              |
| 06.A Chassis                            | OK   | الشاسيه                    |
| <b>07 Interior Condition</b>            |  | <b>الحاله الداخليه</b>     |
| 07.A Roof Ceiling                       | MANUAL ROOF CONVERTIABLE NOT OPEN PROPERLY | بطانه السقف                |
| 07.B Steering Wheel and control buttons | HORN NOT WORKING                           | عجلة القيادة وازرار التحكم |
| 07.C AC Condition                       | OK   | المكيف                     |
| <b>08 Transmission Condition</b>        |  | <b>الجير</b>               |
| 08.A Road Test                          | NOT CHECK                                  | فحص علي الطريق             |
| 08.B Visual Gear Box Condition          | MINOR OIL LEAK & REFITTED                  | حالة الجير النظرى          |
| <b>09 Engine Condition</b>              |  | <b>المحرك</b>              |
| 09.A Visual Engine Condition            | MINOR OIL LEAK & REFITTED                  | حالة المحرك النظرى         |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.