

Queue Number 2792868

Transaction Date 23 Sep 2026, 16:52:14

Site Name  
840 - Emirates AuctionsTransaction Number  
60388813 (CC10009) (CC10012)

## Vehicle Details

|                   |                   |
|-------------------|-------------------|
| Chassis Number    | JTMHY05J6F*****   |
| Specification     | GCC Specification |
| Make              | Toyota            |
| Model             | Land Cruiser      |
| Model Year        | 2015              |
| Color             | Unknown           |
| Mileage           | 157790 Km         |
| Fuel Type         | Petrol            |
| Transmission Type |                   |
| No. Of Cylinders  | 8                 |

## Condition

## Remarks

## الحالة

## 01 Body

## جسم المركبة

|                    |                                                                         |             |
|--------------------|-------------------------------------------------------------------------|-------------|
| 01.A Fenders       | FRONT BOTH SIDE REPAINTED , REAR RIGHT SIDE PORTION DENT                | مدكار       |
| 01.B Paint         | BODY PORTION REPAINTED PORTION REPAIRED MINOR SCRATCHES , PORTION RUSTY | الصبغ       |
| 01.C Doors         | REAR RIGHT SIDE DOOR , SKIRT, PORTION DAMAGED                           | أبواب       |
| 01.D Floor         | FLOOR FULLY MUDDY                                                       | الارضية     |
| 01.E Bumper        | MISALIGN , GRILL FADED                                                  | دعامية      |
| 01.F Bonnet        | REPAINTED PORTION REPAIRED                                              | غطاء المحرك |
| 01.G Vehicle Color | WHITE                                                                   | لون المركبة |

## 02 Chassis Condition

## الشاسي

|              |                                        |         |
|--------------|----------------------------------------|---------|
| 02.A Chassis | CHASSIS MUDDY PORTION GETTING RUSTY/OK | الشاسيه |
|--------------|----------------------------------------|---------|

## 03 Engine Condition

## المحرك

|                              |                                   |                       |
|------------------------------|-----------------------------------|-----------------------|
| 03.A Engine Visual Condition | OIL WET PARTS GTTIG RUSTY OIL WET | الحالة النظرية للمحرك |
|------------------------------|-----------------------------------|-----------------------|

## 04 Transmission Condition

## الجير

|                                |                                            |                      |
|--------------------------------|--------------------------------------------|----------------------|
| 04.A Gear Box Visual Condition | PARTS REFITTED GETTING RUSTY MINOR JERKING | الحالة النظرية للجير |
| 04.B Road Test                 | NOT CHECKED                                | فحص علي الطريق       |

## 05 Tires and Rims Condition

## الاطارات

|                 |                      |                |
|-----------------|----------------------|----------------|
| 05.A Front Tyre | BOTH SIDE 2023 CRACK | الاطار الامامي |
|-----------------|----------------------|----------------|

| Condition                               | Remarks                         | الحالة                     |
|-----------------------------------------|---------------------------------|----------------------------|
| 05.B Rear Tyre                          | BOTH SIDE 2023 CRACK            | الاطار الخلفي              |
| <b>06 Lights</b>                        |                                 | <b>الاضاءة</b>             |
| 06.A Head Light                         | LENS GETTING FADED              | الاضاءة الرئيسية           |
| 06.B Tail Light                         | BOTH SIDE PORTION CRACK         | الضوء الخلفي               |
| <b>07 Interior Condition</b>            |                                 | <b>الحالة الداخلية</b>     |
| 07.A Other                              | INNER PARTS GETTING MINOR RUSTY | اخرى                       |
| 07.B AC Condition                       | OK                              | المكيف                     |
| 07.C Audio                              | REAR RIGHT SIDE LCD SCRATCHES   | صوتيات                     |
| 07.D Steering Wheel and control buttons | WORN OUT                        | عجلة القيادة وازرار التحكم |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](https://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](https://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on [wecare@carcheck.ae](mailto:wecare@carcheck.ae)

للسكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carcheck.ae](mailto:wecare@carcheck.ae)