



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **26 Dec 2022, 13:17:05**
 Transaction Number **23285194 (CC10008)** Queue Number **647665**



Chassis Number **WDDNG56X58A200385**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Mercedes**
 Model **S 500**
 Model Year **2008**
 Color **White**
 Mileage **001 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENT,SCRATCHES ON BODY	الصبغ
01.B Fenders	REAR RIGHT SIDE DENT&REAR LEFT SIDE REPAINTED	مدكار
01.C Doors	RIGHT SIDE BOTH DOOR REPAINTED,PORTION REPAIRED	أبواب
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
01.F Floor	UNDER BODY FULLY COVERED&VISIBLE AREA CHECK ONLY	الارضية
01.G Vehicle Model	S 350	طراز المركبة
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	NOT CHECKED,OIL LEAK	حالة الجير النظري
02.B Road Test	NOT CHECKED	فحص علي الطريق
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2016 CRACKED , EXPIRED ,	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2018/2019 CRACKED	الاطار الخلفي
04 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
04.A Shock Absorber	FRONT LEFT SIDE & REAR RIGHT SIDE OIL LEAK	ممتص الصدمات
04.B Other	BODY LEVEL TOO LOW	اخرى
04.C Arms	LOWER ARM BUSHES CRACKED	ازرع
05 Interior Condition		الحالة الداخلية
05.A Power Window Switch	REAR BOTH SIDE WINDOW CURTAIN PANEL MISSING	مفتاح النافذه
05.B Mirror	RIGHT SIDE INDACTOR COVER CRACKED	المرايا
05.C AC Condition	NOT CHECKED	المكيف
05.D Odometer reading	NOT CHECKED	قراءة عداد المسافات
06 Steering Condition		المقود
06.A Axle	BOOT CUT	اكسلات
07 Engine Condition		المحرك
07.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,MINOR OIL LEAK	حالة المحرك النظرى
08 Lights		الاضاءة
08.A Head Light	LENS FADED,ALL LIGHT NOT CHECK ,BOTH SIDE HEAD LIGHT BRACKET DAMAGED	الاضاءة الرئيسية
09 Chassis Condition		الشاسي
09.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.