

Queue Number	2408773	Transaction Date	25 May 2026, 12:31:10
Site Name	840 - Emirates Auctions	Transaction Number	25744175 (CC10006) (CC10019)



Vehicle Details

Chassis Number	JN6BE6BS3D*****
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2013
Color	White
Mileage	314436 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		
جسم المركبة		
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	BACK PANEL REPAIRED & FRONT FLOORING PORTION RUSTY, WEAK, HOLE	الارضية
01.D Bumper	MISALIGN, PORTION CRACKED	دعامية
02 Chassis Condition		
الشاسي		
02.A Chassis	OK	الشاسية
03 Engine Condition		
المحرك		
03.A Mount	BUSHES CRACKED	كرسي
03.B Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED, REFITTED, MINOR OIL LEAK, PARTS RUSTY	الحالة النظرية للمحرك
04 Seats Condition		
المقاعد		
04.A Seat Condition	REAR SEAT MISSING	حالة المقاعد
05 Transmission Condition		
الجير		
05.A Gear Box Visual Condition	REFITTED, OIL LEAK, PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		
الاطارات		

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2022/2021 WORN OUT, DRY CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021/2020 EXPIRED, WORN OUT, CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE COVER PORTION DAMAGED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	WEAK	ممتص الصدمات
08.B Leaf Spring	BUSHES CUT , LEAF GETTING RUSTY	ازرع عمود التوازن و مثبت عمود التوازن
08.C Arms	LOWER ARM BUSHES CUT	
08.D Stabilizer Bar And Link Rod	BOOT CUT	
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
09.B Mirror	CENTER MIRROR PORTION LOOSE	المرايا
09.C AC Condition	NOT CHECK	المكيف
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae