

## **TEST CERTIFICATE**

Site Number Transaction Number **840-Emirates Auctions** 31146158 (CC10008)

Transaction Date

14 Jun 2022, 13:12:00

**Oueue Number** 

312309

152078 Km



Chassis Number WDBUF41X27B118566

**Engine Number** 

Vehicle Class Car

Manufacturer Mercedes

Model E 200 Model Year 2007

Color White

Fuel Type **Petrol** 

No. Of Cylinders

Specification **GCC Specification** 

DEFECT REMARKS

**01 Interior Condition** الحاله الداخليه

01.A AC Condition **NOT WORKING** المكيف 01.B Steering Wheel and **WORN OUT** عجلة القيادة وازرار التحكم control buttons

01.C Dash Board CENTER CONSOLE BOX LOCK COVER MISSING لوحة القياده

**02 Tires and Rims Condition** الاطارات

02.A Front Tyre **BOTH SIDE 2017 EXPIRED** الاطار الامامى **BOTH SIDE 2017 EXPIRED** 02.B Rear Tyre الاطار الخلفى

**03 Lights** الاضاءة

03.A Warning Light WARNING LIGHT ON IN DISPLAY ضوء تحذير LEFT SIDE BRACKET BROKEN 03.B Head Light الاضاءة الرئيسية

04 Body جسم المركبة

04.A Paint BODY PORTION REPAINTED, PORTION REPAIRED, MINOR الصبغ **DENT, SCRATCHES** 

04.B Fenders FRONT LEFT SIDE REPAINTED, PORTION REPAIRED & MINOR مدكار

**CRACKED &RIGHT SIDE PORTION REPAINTED** 

04.C Doors FRONT RIGHT SIDE REPAINTED أبواب

DEFECT	REMARKS	
04.D Floor	FLOOR COVERED CHECKED VISIBLE AREA OK	الارضية
04.E Bumper	SCRATCHES	دعامية
05 Seats Condition		المقاعد
05.A Seat Condition	FRONT RIGHT SIDE ADJUSTMENT NOT WORKING &NECK BACK WORN OUT	حالة المقاعد
06 Suspension System		ممتص الصدمات
06.A Arms	FRONT CONTROL ARM BUSHES CRACKED	ازرع
07 Engine Condition		المحرك
07.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى
<b>08 Transmission Condition</b>		الجير
08.A Road Test	NOT CHECH	فحص علي الطريق
08.B Visual Gear Box Condition	JERKING	حالة الجير النظرى
09 Chassis Condition		الشاصي
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.