

Queue Number 2845066

Transaction Date 07 Oct 2026, 16:50:43

Site Name
840 - Emirates AuctionsTransaction Number
70744981 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WBATS3A09K*****
Specification	GCC Specification
Make	BMW
Model	X3
Model Year	2019
Color	Gold
Mileage	137389 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, MINOR DENT SCRATCHES	الصبغ
01.B Doors	LEFT SIDE BOTH REPAINTED	أبواب
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COMPLETELY COVERED	الارضية
01.E Bumper	MINOR MISALIGN , GRILL PORTION CRACK	دعامية
01.F Bonnet	SHOCK NOT WORKING	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخرى
02.C Chassis Number	DOOR POST STICKER DAMAGED WORN OUT	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	COMPONENTS REFITTED	الحالة النظرية للمحرك
------------------------------	---------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED , MINOR OIL LEAK	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
06 Interior Condition		الحالة الداخليه
06.A AC Condition	OK	المكيف
06.B Door Panel	PORTION GETTING MELTED	لوحة بطانة الباب
06.C Steering Wheel and control buttons	MINOR SCRATCHES	عجلة القيادة وازرار التحكم
06.D Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae