

## **TEST CERTIFICATE**

Site Number
Transaction Number

840-Emirates Auctions 11847581 (CC10006) Transaction Date

15 Jan 2023, 17:00:36

Queue Number 657297

Chassis Number

1N4AL3AP2JC102043

Car

Engine Number

Vehicle Class

Manufacturer Nissan

Model Altima

Model Year 2018

Color Grey

Mileage **001 Miles** 

Fuel Type Petrol

No. Of Cylinders

Specification

Imported

DEFECT REMARKS

O1.A Roof Light FRONT LOOSE أثارة السقف O1.B AC Condition NOT CHECKED . المكيف O1.C Odometer reading NOT CHECKED .

## O2 Body جسم المركبة

الطبغ BODY PORTION REPAIRED ,REPAINED .MINOR DENTS
SCRATCHES ,

02.B Rusty UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .

02.C Trunk NOT OPEN .

02.D Floor FLOOR PORTION DENT.

## 03 Tires and Rims Condition

O3.A Front TyreBOTH SIDE 2019 CRACKED ,PUNCTURE.BOTH SIDE 2019 CRACKED ,CRACKED .Uddly likelingBOTH SIDE 2017 EXPIRED ,CRACKED .

## ممتص الصدمات ممتض الصدادة O4 Suspension System

DEFECT	REMARKS	
05 Engine Condition		المحرك
05.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED KEY MISSING . MINOR OIL LEAK .	حالة المحرك النظرى
06 Transmission Condition		الجير
06.A Road Test	NOT CHECKED .	فحص علي الطريق
06.B Visual Gear Box	NOT CHECKED .MINOR OIL LEAK .	حالة الجير النظرى
Condition		C5
07 Chassis Condition		الشاصي
07.A Chassis	CHECKED VISIBLE REA OK.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



• شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

• كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.