CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2902350
Transaction Date	23 Oct 2026, 15:59:50
Site Name	840 - Emirates Auctions
Transaction Number	32621396 (CC10009) (CC10012)



Vehicle Details

Chassis Number	WVWGR2AUXH*******
Specification	GCC Specification
Make	Volkswagen
Model	Golf R
Model Year	2017
Color	White
Mileage	195092 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPLETELY COVERED MUDDY NTO VISIBLE PROPERLY	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REFITTED , SHOCK WEAK	غطاء المحرك
01.G Vehicle Model	GOLF	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FULLY MUDDY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH & REMOVE ALL UNDER COVERS CHASSIS COVERED & DIRTY	اخري
03 Engine Condition		المحرك
03.A Other	TURBO REWELDED	اخري
03.B Engine Visual Condition	OPEN REFITTED OVER HEAT , SIGNOF OIL WET,	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACKED	حالة المقاعد
05 Exhaust System		نظام العادم

Condition	Remarks	الحالة
05.A Catalytic Converter	CUT RWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OPEN REFITTED GETTING RUSTY	الحالة النظره للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
07.C Rims Condition	LEFT SIDE HUB COVER MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	EXTRA STICKER , FADED , LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Other	SUSPENSION REFITTED	اخري
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY , CENTER CONSOLE BOX SLIDING COVER NOT WORK	اخري
11.B AC Condition	LOW COOLING , GRILL ADJUSTMENT PORTION MISSING	المكيف
11.C Roof Ceiling	LOOSE	بطانه السقف
11.D Sun Visor	LEFT SIDE LOOSE	حاجب الشمس
11.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.F Sunroof	STRIB PORTION CRACK	فتحت سقف
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae