CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2942117
Transaction Date	04 Nov 2026, 16:46:45
Site Name	840 - Emirates Auctions
Transaction Number	18057612 (CC10009) (CC10011)



Vehicle Details

Chassis Number	JTHKD5BH8H*******
Specification	GCC Specification
Make	Lexus
Model	CT 200 H
Model Year	2017
Color	White
Mileage	222233 Km
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED,RIGHT SIDE BOTH REPAIRED REPAINTED,FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR LEFT PORTION REPAINTED,FRONT LEFT SIDE REPAINTED PORTION REPAIRED & RIGHT SIDE BOTH REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR COVERED PORTION DENT	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.G Windshield	FRONT RIGHT SIDE STRIP MISSING,COWL PANEL COVER PART MISSING	زجاج
01.H Bonnet	REPAIRED REPAINTED,REFITTED	غطاء المحرك
01.I Pillars	RIGHT SIDE A/PILLAR OUTER PANEL ROOF RAIL REPAIRED	القوائم
01.J Trunk	PORTION REPAIRED REPAINTED	صندوق
01.K Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE OUTER JOINT MINOR OPEN	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED ABNORMAL NOISY MINOR OIL LEAK GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DRIVER SEAT COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL WET GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE LENS FADED,WASHER COVER MISSING	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY,WEAK	دواسة الفرامل
08.B Other	ABS WARNING LIGHT	اخري
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX PANEL PORTION WORN OUT, INNER PARTS GETTING RUSTY	اخري
10.B Mirror	RIGHT SIDE INDICATOR LIGHT MISSING	المرايا
10.C AC Condition	OK	المكيف
10.D Dash Board	PORTION GETTING MELTED WORN OUT	لوحة القياده
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.