



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Nov 2022, 12:25:47
Transaction Number	46237743 (CC10006)	Queue Number	631067



Chassis Number	1HGCP2630CA628484
Engine Number	
Vehicle Class	Car
Manufacturer	Honda
Model	Accord
Model Year	2012
Color	Red
Mileage	403341 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Arms	MOUNT RUBBER CUT	ازرع
01.B Ball Joint	BOOT CUT	مفصل كروي
01.C Other	STABLIZER LINK BOOT CUT	اخرى
02 Steering Condition		المقود
02.A Axle	BOOT CUT	اكسلات
02.B Steering Boot	BOOT CUT	ربلة المقود
02.C Tie Rod End	BOOT CUT	مؤخرة الرودادات
02.D Steering Box	OIL LEAK	جهاز المقود
03 Body		جسم المركبة
03.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
03.B Fenders	FRONT REFITTED	مدكار
03.C Windshield	FRONT CRACKED	زجاج
03.D Bonnet	REFITTED	غطاء المحرك
03.E Sign of front accident		وجود مؤشر لحادث في المقدمة
03.F Floor	UNDER BODY COMPLETELY RUST PROOFED	الارضية

DEFECT	REMARKS	
03.G Bumper	MISALIGN	دعامية
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2016 EXPIRED CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2016 EXPIRED CRACKED	الاطار الخلفي
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	OIL LEAK & JERKING	حالة الجير النظرى
05.B Road Test	NOT CHECK	فحص علي الطريق
05.C Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
06 Chassis Condition		الشاصي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07 Lights		الاضاءة
07.A Fog light	MISSING	كشاف الضباب
07.B Head Light	LEFT SIDE LOW BEAM NOT WORKING & LENS FADED	الاضاءة الرئيسية
08 Engine Condition		المحرك
08.A Mount	MOUNT RUBBER CUT	كرسي
08.B Visual Engine Condition	OIL LEAK & MISFIRING	حالة المحرك النظرى
08.C Smoke	WHITE SMOKE	دخان
09 Interior Condition		الحاله الداخليه
09.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.