

Queue Number

2877725

Transaction Date

23 Oct 2026, 15:59:59

Site Name

840 - Emirates Auctions

Transaction Number

37423181 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTGJX02P25*****
Specification	GCC Specification
Make	Toyota
Model	Hiace
Model Year	2005
Color	Yellow
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Pillars	PILLAR DOOR POST REPAIRED.	القوائم
01.F Fuel Tank	DENT,BRACKET LOOSE.	خزان الوقود
01.G Sign of front accident	BUMPER FRAME FENDER FRAME ,FIREWALL COWL PANEL REPAIRED DENT .	وجود مؤشر لحادث في المقدمة
01.H Sign of side accident	RUNNING BOARD ,WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
01.J Vehicle Color	WHITE	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS END CROSS MEMBER DENT GETTING RUSTY.,	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DIRTY LOOSE PORTION DAMAGED .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 WORN OUT	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	CRACKED FADED.	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Leaf Spring	BUSHES CUT .	ازرع مفصل كروي عمود التوازن و مثبت عمود التوازن
09.C Arms	BUSHES CUT .	
09.D Ball Joint	BOOT CUT .,	
09.E Stabilizer Bar And Link Rod	BUSHES CUT .	
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخرى
11.B Mirror	LOOSE FADED	المرآيا
11.C Dash Board	DAMAGED GLOVE BOX MISSING	لوحة القيادة
11.D Roof Ceiling	LOOSE.	بطانة السقف
11.E Sun Visor	LOOSE.	حاجب الشمس
11.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae