

Queue Number 2870371

Transaction Date 15 Oct 2026, 14:55:33

Site Name
840 - Emirates AuctionsTransaction Number
17191100 (CC10008) (CC10025)

Vehicle Details

Chassis Number	1C4PJMDS2H*****
Specification	GCC Specification
Make	Jeep
Model	Cherokee
Model Year	2017
Color	Grey
Mileage	85315 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED REITTED	مدكار
01.B Paint	BODY PORTION REPAINTED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED , FRONT LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN	دعامية
01.F Trunk	MISALIGN	صندوق
01.G Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED PORTION GETTING RUSTY ,CHECKED VISIBLE AREA / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK ,PARTS GETTING RUSTY ,OIL MIX WITH COOLANT WATER ,OVER HEAT ,COMPONENTS REFITTED	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES,EACH RIM ONE BOLT MISSING	حالة الجنوط
06 Brake Condition		الفرامل
06.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES MINOR CRACK	ازرع
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CRACK	مؤخرة الرودادات
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED , CENTER CONSOLE BOX PORTION LOOSE ,	اخرى
09.B AC Condition	OK , REAR GRILL PORTION DAMAGED	المكيف
09.C Dash Board	WORN OUT	لوحة القيادة
09.D Roof Ceiling	PORTION LOOSE	بطانه السقف
09.E Door Panel	PORTION WORN OUT , PORTION DAMAGED	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Sunroof	SUNROOF CURTAIN WHILE FULL OPENING PORTION LOOSE	فتحت سقف
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	OIL MIX WITH COOLANT WATER	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae