

TEST CERTIFICATE


Site Number Transaction Number **840-Emirates Auctions** 80684445 (CC10013)

Transaction Date

24 May 2023, 10:39:32

Queue Number

724366



Chassis Number JT8BL69S410003703

Engine Number

Vehicle Class Car

Manufacturer Lexus

GS 430 Model

Model Year 2001

Gold Color

001 Miles Mileage

Fuel Type **Petrol**

No. Of Cylinders

Imported

REMARKS DEFECT

| 01 Body | | جسم المركبة |
|----------------------------------|---|---------------------------|
| 01.A Fenders | MISALIGN | مدكار |
| O1.B Floor | UNDER FLOOR CHASSIS SUSPENSION PARTS NOT CHECK | الارضية |
| 01.C Sign of back accident | | وجود مؤشر لحادث في الخلف |
| 01.D Paint | BODY PORTION REPAINTED PORTION REPAIRED PORTION RUSTY & FADED MNOR DENT SCRATCHES | الصبغ |
| 01.E Sign of side accident | | وجود مؤشر لحادث في الجانب |
| 01.F Bumper | MISALIGN FADED PORTION CRACK | دعامية |
| 01.G Floor | UNDER FLOOR CHASSIS SUSPENSION PARTS NOT CHECK | الارضية |
| 01.H Bonnet | SHOCK WEAK | غطاء المحرك |
| 01.I Other | VISUAL TEST ONLY | اخري |
| O1.J Windshield | FRONT CRACK | زجاج |
| 02 Transmission Condition | | الجير |

02.A Visual Gear Box NOT CHECK حالة الجير النظرى

Condition

02.B Road Test **NOT CHECK** فحص علي الطريق

03 Seats Condition المقاعد

| DEFECT | REMARKS | |
|---|--|----------------------------|
| 03.A Seat Condition | PORTION DAMAGED | حالة المقاعد |
| 04 Tires and Rims Condition | | الاطارات |
| 04.A Rear Tyre | CRACKED DAMAGED | الاطار الخلفي |
| 04.B Front Tyre | CRACKED DAMAGED | الاطار الامامي |
| 05 Chassis Condition | | الشاصي |
| 05.A Chassis | NOT CHECK | الشاسيه |
| 06 Brake Condition | | الفرامل |
| 06.A Disc&Drum | RUSTY | دسك وطنابير الفرامل |
| 07 Interior Condition | | الحاله الداخليه |
| 07.A Power Window Switch | MAIN SWITCH LOOSE REAR RIGHT SIDE NOT WORKING | مفتاح النافذه |
| 07.B Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 07.C AC Condition | NOT CHECK | المكيف |
| 07.D Dash Board | PORTION DAMAGED | لوحة القياده |
| 08 Lights | | الاضاءة |
| 08.A Head Light | LENS FADED ALL LIGHT NOT CHECK | الاضاءة الرئيسية |
| 09 Engine Condition | | المحرك |
| 09.A Visual Engine Condition | ENGINE NOT START ALL SYSTEM NOT CHECK OIL LEAK | حالة المحرك النظرى |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.