



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>11 Jan 2022, 17:26:03</b>
Transaction Number	<b>87940882 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDCYC3GF1DX203783</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>G 63</b>
Model Year	<b>2013</b>
Color	<b>White</b>
Mileage	<b>111984 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Steering Wheel and control buttons	AUDIO BUTTON FADED	عجلة القيادة وازرار التحكم
01.B Dash Board	DASHBAORD LEATHER LOOSE	لوحة القيادة
01.C Sun Visor	BOTH SIDE GLASS COVER MISSING	حاجب الشمس
01.D Power Window Switch	BUTTON FADED	مفتاح النافذه
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Warning Light	WARNING MESSAGE ON IN DISPLAY	ضوء تحذير
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Doors	REPAINTED	أبواب
03.B Trunk	REPAINTED	صندوق
03.C Paint	PORTION REPAINTED	الصبغ
03.D Fenders	REAR BOTH SIDE &FRONT RIGHT SIDE REPAINTED&FRONT REFITTED	مدكار
03.E Roof	REPAINTED&PORTION RUSTY	السقف
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	OK	الشاسيه

DEFECT	REMARKS	
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك
<b>06 Seats Condition</b>		<b>المقاعد</b>
06.A Seat Condition	OK	حالة المقاعد
06.B Seat Belt	OK	حزام الأمان
<b>07 Wipers and Arms</b>		<b>المساحات</b>
07.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Oil	OIL LEAK	زيت المقود
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
09.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
<b>10 Transmission Condition</b>		<b>الجير</b>
10.A Road Test	NOT CHECK	فحص علي الطريق
10.B Gear Box	SIGN OF OIL WET	الجير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.