CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3008814
Transaction Date	18 Nov 2026, 16:41:37
Site Name	840 - Emirates Auctions
Transaction Number	57723846 (CC10010) (CC10010)



Vehicle Details

Chassis Number	VF1LZLET4E*******
Specification	GCC Specification
Make	Renault
Model	Fluence
Model Year	2014
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT & REAR BOTH SIDE REPAINTED PORTOION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	FRONT RIGHT SIDE REAR BOTH SIDE REPAINTED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Windshield	FRONT WINDSHIELD CRACKED .	زجاج
01.H Door Handle &Lock	BOTH SIDE OUTER HANDLE MISSING.	مقابض الأبواب والأقفال
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2020 EXPIRED CRACKED .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 EXPIRED CRACKED .	الاطار الخلفي
06 Lights		**الاضاءة**
06.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07 Brake Condition		**الفرامل**
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		**ممتص الصدمات**
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Steering Condition		**المقود**
09.A Steering Boot	CUT	ربلة المقود
09.B Steering Box	OIL LEAK	جهاز المقود
09.C Axle	BOOT CUT	اكسلات
10 Interior Condition		**الحاله الداخليه**
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	CENTER MIRROR MISSING	المرايا
10.C AC Condition	NOT CHECKED.	المكيف
10.D Dash Board	PORTION LOOSE	لوحة القياده
10.E Odometer reading	NOT CHECKED .	قراءة عداد المسافات
10.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.