CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3013173
Transaction Date	20 Nov 2026, 10:56:24
Site Name	840 - Emirates Auctions
Transaction Number	22075825 (CC10008) (CC10008)



Vehicle Details

Chassis Number	WP1ZZZ92ZG*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2016
Color	White
Mileage	88161 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED REFITTED ,REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT,SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER BODY COVERED MUDDY FOR PROPERLY INSPECTION REMOVE FENDER COVER UNDER COVER ,CLEAN CHASSIS	الارضية
01.E Bonnet	REPAINTED ,REFITTED	غطاء المحرك
01.F Door Handle &Lock	FRONT LEFT SIDE OUTER SMART LOCK BUTTON MISSING	مقابض الأبواب والأقفال
01.G Fuel Tank	FUEL LEAK ,TANK COVER DAMAGED	خزان الوقود
01.H Sign of front accident	FENDER FRAME RADIATOR SUPPORT ,BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED ,OIL WET ,OIL MIX WITH COOLANT	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT LEFT SIDE SEAT ADJUSMENT ONE BUTTON MISSING ,SEAT PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Gear Box Mount	CRACK	كرسي الجير
05.C DIFFERENTIAL	REAR MOUNT BUSHES CRACK	الدفرنشل
05.D Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 INNER GETTING WORN OUT	الاطار الخلفي
06.C Rims Condition	FRONT LEFT SIDE ,REAR RIGHT SIDE ONE BOLT MISSING	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	WATER TANK DAMAGED	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Warning Light	WARNING MESSAGE SHOW ON DISPLAY	ضوء تحذير
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING MINOR RUSTY	اخري
09.B AC Condition	OK/GRILL ADJUSTMENT ,CHROME BUTTON MISSING	المكيف
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	OIL MIX WITH COOLANT	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae