CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2923847
Transaction Date	31 Oct 2026, 12:49:48
Site Name	840 - Emirates Auctions
Transaction Number	13302222 (CC10009) (CC10025)



Vehicle Details

Chassis Number	WBAFG2103D*******
Specification	GCC Specification
Make	BMW
Model	X6
Model Year	2013
Color	White
Mileage	98200 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT FIBER PAINT NOT CHECK , LEFT SIDE REFITTED	مدكار
01.B Paint	BODY MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
01.G Bonnet	SHOCK NOT WORKING , GRILL LOOSE	غطاء المحرك
01.H Trunk	LUGGAGE SHADE MISSING, AUTO SWITCH COVER MISSING	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Other	AIR INTAKE PIPE TIED BY TAP	اخري
03.C Engine Visual Condition	ENGINE FUALT /OIL LEAK REFITTED GETTING RUSTY,SHAKING, GET NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CUT , REAR LOOSE	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION REFITTED	اخري
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
09.B Other	STEERING HAVE MAJOR PLY & NOISY	اخري
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX SLIDING COVER DAMAGED/ INNER PARTS GETTING RUSTY	اخري
10.B Mirror	ADJUSTMENT NOT WORKING	المرايا
10.C AC Condition	OK , SWITCH PORTION FADED	المكيف
10.D Roof Ceiling	PORTION LOOSE	بطانه السقف
10.E Door Panel	WORN OUT , PORTION LOOSE	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.