

Queue Number 2762097

Transaction Date 21 Sep 2026, 13:49:14

Site Name  
840 - Emirates AuctionsTransaction Number  
41344058 (CC10009) (CC10012)

## Vehicle Details

|                   |                 |
|-------------------|-----------------|
| Chassis Number    | SALYB2EX1K***** |
| Specification     | Imported        |
| Make              | Range Rover     |
| Model             | Velar           |
| Model Year        | 2019            |
| Color             | White           |
| Mileage           | 121567 Miles    |
| Fuel Type         | Petrol          |
| Transmission Type |                 |
| No. Of Cylinders  | 4               |

| Condition | Remarks | الحالة |
|-----------|---------|--------|
|-----------|---------|--------|

| 01 Body                     |                                                              | جسم المركبة                |
|-----------------------------|--------------------------------------------------------------|----------------------------|
| 01.A Fenders                | FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED        | مدكار                      |
| 01.B Paint                  | BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES | الصبغ                      |
| 01.C Doors                  | REPAINTED PORTION REPAIRED                                   | أبواب                      |
| 01.D Rusty                  | UNDER BODY PARTS SUSPENSION GETTING RUSTY                    | صدأ                        |
| 01.E Bonnet                 | REPAINTED PORTION REPAIRED , REFITTED , SHOCK WEAK NOT WORK  | غطاء المحرك                |
| 01.F Sign of front accident | FRONT BUMPER BULK HEAD ASSEMBLTY REFITTED                    | وجود مؤشر لحادث في المقدمة |

| 02 Chassis Condition |                                                                          | الشاسي  |
|----------------------|--------------------------------------------------------------------------|---------|
| 02.A Chassis         | CHASSIS FULLY COVERED COVERED OILY PORTION MINOR DENT,OK                 | الشاسيه |
| 02.B Other           | FOR RE CHECKED PROPERLY REMOVE ALL UNDER FENDER COVERS & MAKE STEAM WASH | اخرى    |

| 03 Engine Condition          |                                                               | المحرك                |
|------------------------------|---------------------------------------------------------------|-----------------------|
| 03.A Engine Visual Condition | OIL LEAK OPEN REFITTED, SHAKING GETTING RUSTY, ABNORMAL NOISY | الحالة النظرية للمحرك |

| 04 Seats Condition  |                                | المقاعد      |
|---------------------|--------------------------------|--------------|
| 04.A Seat Condition | PORTION CUT , BACK COVER LOOSE | حالة المقاعد |

| 05 Transmission Condition      |                                                  | الجير                |
|--------------------------------|--------------------------------------------------|----------------------|
| 05.A Gear Box Visual Condition | GEAR FAULT ,MINOR OIL LEAK OPENR EFITTED JERKING | الحالة النظرية للجير |
| 05.B DIFFERENTIAL              | TRANSMISSION MODES NOT WORKING                   | الدفرنشيل            |

| Condition                               | Remarks                                                                                             | الحالة                     |
|-----------------------------------------|-----------------------------------------------------------------------------------------------------|----------------------------|
| 05.C Road Test                          | NOT CHECKED                                                                                         | فحص علي الطريق             |
| <b>06 Tires and Rims Condition</b>      |                                                                                                     | <b>الاطارات</b>            |
| 06.A Front Tyre                         | BOTH SIDE 2025                                                                                      | الاطار الامامي             |
| 06.B Rear Tyre                          | BOTH SIDE 2024                                                                                      | الاطار الخلفي              |
| <b>07 Lights</b>                        |                                                                                                     | <b>الاضاءة</b>             |
| 07.A Head Light                         | LENS GETTING FADED                                                                                  | الاضاءة الرئيسية           |
| 07.B Tail Light                         | RIGHT SIDE SPOT CRACK                                                                               | الضوء الخلفي               |
| 07.C Warning Light                      | WARNING LIGHT ON DISPLAY                                                                            | ضوء تحذير                  |
| <b>08 Brake Condition</b>               |                                                                                                     | <b>الفرامل</b>             |
| 08.A Brake Pedal                        | SPONGY WEAK                                                                                         | دواسة الفرامل              |
| <b>09 Suspension System</b>             |                                                                                                     | <b>ممتص الصدمات</b>        |
| 09.A Arms                               | BUSHES CRACKED                                                                                      | ازرع                       |
| 09.B Other                              | SUSPENSION REFITTED                                                                                 | اخرى                       |
| <b>10 Interior Condition</b>            |                                                                                                     | <b>الحالة الداخلية</b>     |
| 10.A Other                              | INTERIOR PARTS RUSTY SIGN OF FLOODED, CENTER CONSOLE BOX WORN OUT , PORTION STICKER, ELECTRIC FAULT | اخرى                       |
| 10.B Mirror                             | AUTO BUTTON LOOSE                                                                                   | المرآيا                    |
| 10.C AC Condition                       | NOT COOLING                                                                                         | المكيف                     |
| 10.D Power Window Switch And Glass      | PANEL SWITCH LOOSE                                                                                  | مفتاح النافذه و الزجاج     |
| 10.E Roof Ceiling                       | LOOSE                                                                                               | بطانه السقف                |
| 10.F Steering Wheel and control buttons | WORN OUT                                                                                            | عجلة القيادة وازرار التحكم |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](https://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](https://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

للشكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)