CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934014
Transaction Date	02 Nov 2026, 14:32:25
Site Name	840 - Emirates Auctions
Transaction Number	45780512 (CC10026) (CC10026)



Vehicle Details

Chassis Number	MDHBN7ADXE*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2014
Color	White
Mileage	204449 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUSTY PROOFED PORTION DENTS	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGE , TOW HOOK COVER MISSING	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك
01.G Trunk	REFITTED	صندوق
01.H Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis Extension	BOTH SIDE CHASSIS EXTENSION END , REPAIRED	تمديدات الشاسي
02.B Chassis	FRONT BOTH SIDE CHASSIS REPAIRED , DENT	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK , SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , SIGN OF OIL LEAK , MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
08.B AC Condition	LOW COOLING	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القياده
08.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
08.E Door Panel	PORTION DAMAGE	لوحة بطانة الباب
08.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
08.H Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	COVER MISSING , EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae