

Queue Number 2852638

Transaction Date 10 Oct 2026, 12:46:32

Site Name
840 - Emirates AuctionsTransaction Number
95753256 (CC10009) (CC10012)

Vehicle Details

Chassis Number	2LMPJ8J97K*****
Specification	GCC Specification
Make	Lincoln
Model	Nautilus
Model Year	2019
Color	Black
Mileage	90257 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY MINOR DENT SCRATCHES	الصيغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY MUDDY	صدأ
01.C Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.D Bumper	LEFT SIDE STRIP PORTION CRACK	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETEY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY, MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص على الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2026 , RIGHT SIDE 2025	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
08.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae