



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 Sep 2022, 13:07:34**
 Transaction Number **27244717 (CC10009)** Queue Number **595639**



Chassis Number **WDDNG79X37A124994**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Mercedes**
 Model **S 65 AMG**
 Model Year **2007**
 Color **White**
 Mileage **167348 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **12**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Engine Condition		المحرك
03.A Visual Engine Condition	OIL LEAK & REFITTED	حالة المحرك النظري
04 Body		جسم المركبة
04.A Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA & COVER PORTION DAMGED	الارضية
04.B Paint	BODY MINOR SCRATCHES	الصبغ
05 Chassis Condition		الشاسي
05.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	FRONT LEFT SIDE LEAK	ممتص الصدمات
06.B Arms	LOWER ARM BUSH CRACKED	ازرع

DEFECT	REMARKS	
06.C Ball Joint	BOOT CUT	مفصل كروي
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
07.B Road Test	NOT CHECK	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.