



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	20 May 2023, 12:25:01
Transaction Number	32632672 (CC10008)	Queue Number	722104



Chassis Number	2B3KA53HX6H283159
Engine Number	
Vehicle Class	Car
Manufacturer	Dodge
Model	Charger RT
Model Year	2006
Color	Blue
Mileage	290556 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Rims Condition	RIMS HAVE MINOR DENT,SCRATCHES	حالة الجنوط
01.B Front Tyre	BOTH SIDE 2018 EXPIRED,CRACKED,DAMAGED	الاطار الامامي
01.C Rear Tyre	BOTH SIDE 2018 EXPIRED,CRACKED,DAMAGED	الاطار الخلفي
02 Interior Condition		الحاله الداخليه
02.A Roof Ceiling	BOTH GRIP HANDLE DAMAGED,MISSING	بطانه السقف
02.B Dash Board	EXTRA SWITCH MODIFIED	لوحة القيادة
02.C AC Condition	NOT CHECKED	المكيف
02.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.E Other	GEAR SHIFTING LEVER CONSOLE BOX COVER MISSING	اخرى
02.F Mirror	CENTER MIRROR FADED	المرايا
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	NOT CHECKED ,REFITTED& SHIFTING CABLE FIXED BY WIRE	حالة الجير النظري
03.B Propeller Shaft	FLANGE RUBBER CRACKED	ناقل الحركة
04 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
04.A Other	STAIBILZER MOUNT BUSHES MISSING MOUNT BOLT MISSING	اخرى
04.B Ball Joint	BOOT CUT	مفصل كروي
04.C Coil Spring	REAR COIL SPRING HEATED	ياي حلزوني
04.D Arms	LOWER ARM BUSHES CRACKED	ازرع
04.E Suspension Subframe	FRONT SUBFRAME DENT	
05 Body		جسم المركبة
05.A Vehicle Color	BLUE / BLACK	لون المركبة
05.B Floor	PORTION DENT& RUNNING BOARD COVER DAMAGED	الارضية
05.C Paint	BODY REPAINTED,PORTION REPAIRED, DENT,SCRATCHES,PORTION RUSTY ,PORTION FADED	الصبغ
05.D Bumper	DAMAGED,LOOSE	دعامية
05.E Rusty	UNDER SUSPENSION PARTS,GETTING RUSTY	صدأ
06 Lights		الاضاءة
06.A Indicator & Hazard light	FRONT BOTH SIDE ASSEMBLY MISSING	الاشارات
06.B Head Light	LENS FADED ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
07 Steering Condition		المقود
07.A Steering Oil	OIL LEAK	زيت المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادت
08 Engine Condition		المحرك
08.A Visual Engine Condition	ENIGNE NOT START ALL SYSTEM NOT CHECKED ,OIL LEAK,REFITTED	حالة المحرك النظري
09 Exhaust System		نظام العادم
09.A Other	REAR LEFT SIDE PIPE BEND ,BROKEN & PIPE & MUFILER MISSING & BRACKET DAMAGED,RUBBER MISSING	اخرى
10 Seats Condition		المقاعد
10.A Seat Condition	PORTION DAMAGED	حالة المقاعد
11 Chassis Condition		الشاسي
11.A Chassis	FRONT RIGHT SIDE CHASSIS MINOR BEND	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

