CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877710
Transaction Date	20 Oct 2026, 10:43:11
Site Name	840 - Emirates Auctions
Transaction Number	10017301 (CC10010) (CC10010)



Vehicle Details

Chassis Number	1FAHP2KT1F*******
Specification	GCC Specification
Make	Ford
Model	Taurus
Model Year	2015
Color	Black
Mileage	97101 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	BOTH SIDE MIDDLE FLOOR DENT .	الارضية
01.D Bumper	MISALIGN ,SCRATCHES.	دعامية
01.E Bonnet	REPAIRED REPAINTED REFITTED.	غطاء المحرك
01.F Trunk	REPAINTED	صندوق
01.G Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	NEED TO REMOVE FENDER COVER UNDER FOR FOR INSPECTION .	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,PARTS REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED WORN OUT .	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
06 Brake Condition		الفرامل
06.A Disc&Drum	PARTS RUSTY..	دسك وطنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK .	ممتص الصدمات
07.B Arms	BUSHES CRACKED.	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY .SIGN OF FLOODED	اخري
08.B AC Condition	NOT CHECKED .	المكيف
08.C Steering Wheel and control buttons	GETTING WORN OUT.	عجلة القيادة وازرار التحكم
08.D Gear Shifting Lever	GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae