



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>22 Jan 2023, 17:05:10</b>
Transaction Number	<b>48288677 (CC10006)</b>	Queue Number	<b>657803</b>



Chassis Number	<b>KMHM61D64U144044</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Hyundai</b>
Model	<b>Coupe</b>
Model Year	<b>2004</b>
Color	<b>Red</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT CHECK	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب
01.D Dash Board	PORTION DAMAGED	لوحة القيادة
01.E Other	CENTER CONSOLE BOX & GEAR LEVER KNOB DAMAGED	اخرى
01.F Odometer reading	NOT CHECK	قراءة عداد المسافات
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Bonnet	REFITTED,SHOCK WEAK,LOGO MISSING	غطاء المحرك
03.B Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
03.C Floor	PORTION DENT	الارضية
03.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,PORTION GETTING RUSTY	الصبغ
03.E Bumper	MISALIGN,PORTION DAMAGED	دعامية

DEFECT	REMARKS	
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Rear Tyre	BOTH SIDE 2016 CRACKED , EXPIRED ,	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2016 CRACKED , EXPIRED ,	الاطار الامامي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Other	STABILIZER LINK BOOT CUT	اخرى
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Arms	LOWER ARM BUSH CRACKED	ازرع
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Visual Gear Box Condition	NOT CHECK,OIL LEAK	حالة الجير النظري
07.B Road Test	NOT CHECK	فحص علي الطريق
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK	حالة المحرك النظري
<b>09 Steering Condition</b>		<b>المقود</b>
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.