CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941838
Transaction Date	04 Nov 2026, 16:46:43
Site Name	840 - Emirates Auctions
Transaction Number	81129263 (CC10009) (CC10019)



Vehicle Details

Chassis Number	TRUMF28J79*******
Specification	GCC Specification
Make	Audi
Model	TT
Model Year	2009
Color	Unknown
Mileage	121261 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Bumper	MISALIGN,LOGO MISSING	دعامية
01.D Roof	CONVERTIBLE ROOF FABRIC PORTION DAMAGED	السقف
01.E Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.F Vehicle Color	WHITE	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	SHAKING GETTING PARTS REFITTED OIL WET	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY,MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 WORN OUT	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحاله الداخليه
10.A Other	INETRIOR PARTS GETTING RUSTY,WATER FLOODED	اخري
10.B Mirror	LEFT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
10.C AC Condition	OK	المكيف
10.D Audio	LOOSE	صوتيات
10.E Door Panel	PORTION DAMAGED,LOOSE	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	DUST COVER PORTION DAMAGED & KNOB WORN OUT	ذراع نقل السرعات
10.H Gear Shifting Lever	DUST COVER PORTION DAMAGED,KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae