CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899783	Transaction Date	26 Oct 2026, 11:16:49
Site Name	840 - Emirates Auctions	Transaction Number	80631113 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WBAKB4107C*******
Specification	GCC Specification
Make	BMW
Model	740 LI
Model Year	2012
Color	White
Mileage	236679 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	RIGHT SIDE FRONT & REAR REAPINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.C Doors	RIGHT SIDE PORTION REPAINTED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.G Bonnet	STAY SHOCK WEAK .	غطاء المحرك
01.H Sign of front accident	FRONTR ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	REMOVE FENDER COVER UNDER COVER STEAM WASH CHASSIS FOR RECHECK	اخري
03 Engine Condition		**المحرك**
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY/AIR FILTER PIPE MISSING	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK „COMPONENT PARTS RUSTY.NOT WORKING ,	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH ASIDE 2023 CRACKED WORNO UT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED. NOT WORKING PROPERLY ,SWITCH MELTED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT/WARNING MESSAGE ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	HARD „	دواسة الفرامل
07.B Disc&Drum	RUSTY .	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK WEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
08.C Stabilizer Bar And Link Rod	BUSHES CUT /.	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Boot	CRACKED.	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B AC Condition	OK	المكيف
10.C Audio	SCREEN NOT WORKING	صوتيات
10.D Roof Ceiling	LOOSE	بطانه السقف
10.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Sunroof	HEAT SHIELD DAMAGED LOOSE	فتحت سقف
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY.	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**