

Queue Number 2837246

Transaction Date 06 Oct 2026, 13:43:39

Site Name
840 - Emirates AuctionsTransaction Number
93209292 (CC10021) (CC10021)

Vehicle Details

Chassis Number WBANE31057*****
 Specification GCC Specification
 Make BMW
 Model 530i
 Model Year 2007
 Color White
 Mileage N/A NA
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	MINOR MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE ARAE ONLY PORTION DENT	الشاسيه
--------------	--	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition	المقاعد
--------------------	---------

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition	الجير
---------------------------	-------

05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

06 Tires and Rims Condition	الاطارات
-----------------------------	----------

06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
-----------------	-----------------	----------------

Condition	Remarks	الحالة
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنايير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Oil	LEAK	زيت المقود
10.B Steering Boot	CUT	ربلة المقود
10.C Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS RUSTY, SIGN OF WATER FLOODED	اخرى
11.B AC Condition	NOT CHECK	المكيف
11.C Door Panel	WORN OUT	لوحة بطانة الباب
11.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.E Gear Shifting Lever	NOT CHECK	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae